

ПРАЙС-ЛИСТ

Переходы Концентрические ГОСТ 17378-2001 сталь 20

DxD	3 (3,5)x3	4x4 (3)	4,5x3,5 (3)	5x4 (3,5)	5x5	6x4	6x5 (4,5)	6x6	7x4,5 (5)	8x6	8x8	10x8	10x10	12x10	12x12	14x12
32x25	3,99	6,30														
38x25	4,35	7,87														
38x32	4,14	7,61														
45x25	4,41	4,98			11,44											
45x32	4,14	4,72			11,13											
45x38	3,88	4,46			10,81											
57x25	5,93	6,30		6,30		7,35										
57x32	6,09			6,30		7,14										
57x38	5,77			6,30		6,93										
57x45	5,77			6,30		6,93										
76x38	7,35					8,76										
76x45	7,35					8,76										
76x57	5,98			7,61	7,61		7,61			35,59						
89x45	7,66					10,18				13,33						
89x57	7,35			9,55		9,55				12,39		29,87				
89x76	6,98			9,24			12,07	12,07		12,07		29,55				
108x57		8,66		12,07		12,07				15,90		62,26				
108x76		8,29					11,13			15,22		61,63				
108x89		7,98			10,50			10,50			14,59		61,00			
114x57		9,71				13,33				17,79		25,41		28,61		
114x76		9,29				12,70				17,79			25,41		28,61	
114x89		8,55						11,76			16,53		22,89		26,04	67,35
114x108					38,76			46,51			50,82	95,28				
133x57		15,96						24,78		24,78		69,87				
133x76				15,96				24,78		24,78		76,23				
133x89			14,59				22,26	22,26				45,72				
133x108				13,96			21,57	21,57		22,64		33,02	33,02			
133x114				13,96			21,57	21,47		22,64		33,02	33,02			
159x57			17,27			27,93		27,93		27,93		34,28		41,31		
159x76			17,27			27,93		27,93		27,93		34,28		41,31		
159x89			18,58			26,04		26,04		28,61		35,59		43,83		
159x108			17,95			25,41				27,93		34,91		43,20		
159x114			17,95			25,41				27,93		34,91		43,20		
159x133			17,27			24,78		24,78			27,30		34,28	42,52		
219x57						42,52				47,67		114,34				
219x76						42,52				47,67		114,34				
219x89						42,52				47,67		114,34				
219x108						42,52				47,67		57,22		101,64		114,34
219x114						42,52				47,67		57,22		101,64		114,34

DxD	3x3 (3,5x3)	4x4 (4x3)	4,5x3,5 (3)	5x4 (5x3,5)	5x5	6x4	6x5 (4,5)	6x6	7x4,5 (5)	8x6	8x8	10x8	10x10	12x10	12x12	14x12
219x133						40,53				48,30		52,71		69,82		120,75
219x159						39,30				46,98		52,71	65,41	85,78		85,78
273x108									59,74			76,23		95,28		
273x114									59,74			76,23		92,28		
273x133									59,74			92,13		114,34		
273x159									69,72	76,23		87,67		107,99		
273x219									68,40		74,97	86,41		106,68		177,87
325x108										86,36		104,79		104,79		
325x114										86,36		104,79		104,79		
325x133										98,96		98,96		139,75		
325x159										86,36		87,67		104,79		
325x219										86,36		103,53		118,12		
325x273										85,95			102,27		116,86	
377x159												358,57		412,91		539,96
377x219												239,08		269,95		419,26
377x273												212,52		244,54	317,62	
377x325												199,23		228,69		292,21
426x159												338,62				520,80
426x219												332,06		368,55		495,49
426x273												258,98		266,80		457,38
426x325												212,62		257,25		
426x377													212,62		241,50	
530x219												796,95		814,45		
530x273												796,95		814,45		
530x325												585,90		600,00		720,56
530x377												573,61		594,86		714,42
530x426												540,09		561,47		703,08

Переходы Эксцентрические ГОСТ 17378-2001 сталь 20

DxD	3x3 (3,5x3)	4x4 (4x3)	4,5x3,5 (3)	5x4 (3,5)	5x5	6x4	6x5 (4,5)	6x6	7x4,5 (5)	8x6	8x8	10x8	10x10	12x10	12x12	14x12
Э 57x45		23,13		24,52			48,05									
Э 76x57	25,48						27,72									
Э 89x45	36,06					37,91				70,56						
Э 89x57	30,07					34,72				68,60						
Э 89x76	24,02						30,52			73,92						
Э 108x57		51,74				52,00				101,36						
Э 108x76		28,67					36,96			97,44						
Э 108x89		28,67						36,96			119,28					
Э 133x108				69,32						79,46						
Э 159x108			88,70	88,70						120,12		174,72		227,36		
Э 159x133			69,32	69,32				86,85			110,88		186,76			
Э 219x159						143,24	143,24			148,56		192,19		617,12		
Э 273x219									231,00	231,00		277,20		316,00		
Э 325x273										327,09	327,09		360,36	421,34		

ПЕРЕХОДЫ ОЦИНКОВАННЫЕ + 10% К ДАННОЙ ЦЕНЕ!!!